


DUCTED WITH CEILING ASSEMBLY

With a ducted application, you will typically see a grill on the ceiling that will look like one of these examples:



The Mach 8 will be compatible with these types of applications (unless there is a heat strip)

HEAT STRIP

If the old unit had a heat strip, the old heat strip will not fit into the Mach 8.

The replacement heat strip for the Mach 8 would be part number 47233-4551.

NON-DUCTED CEILING ASSEMBLY

If your ceiling assembly looks like one of these examples, you would need to replace the fabric duct collar for the ceiling assembly with part number 9330A4541 to match up to the Mach 8.



DUCTED WITH NO CEILING ASSEMBLY

If your AC is mounted from the roof to ductwork in the ceiling, with no ceiling grill on the inside of the coach, this would be considered a “Top-Down Mount” application. There may be modifications required for the Mach 8 to replace the original unit. The coach manufacturer would need to provide information regarding the necessary modifications.